Last Review Date: 07/23/2018

# DOCUMENT MANAGEMENT SYSTEM Page 1 of 1

Doc# UT02-29-SJP

SECURING SLUDGE SAMPLE NFT Title:

Issue Dt: 03/31/2015 Revision Dt:07/23/2018 Review Interval:24 Cat: Safety Doc Type:

Auth:

SECURING SLUDGE SAMPLE NFT Desc:

Loc: Midwest - Plant Maintenance Service-Midwest - Plant Maintenance-Midwest-Gary Works

#### **PURPOSE** 1.0

# SECURING SLUDGE SAMPLE NFT

# 2.0 **HAZARDS**

FALL/SLIP/TRIP

SPILLING SAMPLE/SLUDGE SPLASH

SKIN CONTACT

UNREPORTED PROBLEMS AFFECT YOU AND YOUR FELLOW WORKERS

# 3.0 PERSONAL PROTECTIVE EQUIPMENT

**HARDHAT** SAFETY SHOES SAFETY GLASSES LONG SLEEVE SHIRT **GLOVES** 

# 4.0 **TOOLS AND EQUIPMENT**

#### **5.0** PRECAUTIONS AND LIMITATIONS

# 6.0 PRE-REQUISITE ACTIONS, PERMITS, OR FORMS

### 7.0 WORK PROCEDURE

COLLECTING SAMPLE	USE HANDRAIL GOING DOWN STAIRS.
HOLDING BEAKER	HOLD CONE UNDER OUTLET OF COPPER TUBING LINE AT PUMP SLOWLY OPEN VALVE ON LINE — LET IT RUN FOR 1 MINUTE FILL CONE AND CLOSE VALVE
RECORD READING	READ AND RECORD CONE READING AFTER ONE HOUR, THEN EMPTY CONE. RINSE AND WIPE CLEAN. MAKE ADJUSTMENTS TO WASTING AND/OR RECYCLE RATES AS APPROPRIATE.
CLEANING AREA	WASH DOWN SAMPLE AREA IF NEEDED
REPORT PROBLEMS	VERIFY BOTH VALVES ARE IN PROPER POSITION. IF THERE IS AN ISSUE, NOTIFY THE MANAGER.

UncontPagelledfopy Print Date: 7/25/2018 8:28:08 AM Uncontro.